

**Government of Jammu and Kashmir,
Ladakh Autonomous Hill Development Council, Leh.
Office of the Executive Engineer, Construction Division Leh**

NO:CDL/ *RU/733*

Dated:-*29*/05/2018.

The Principal Kendriya Vidyalaya,
Leh Ladakh.

**Subject:- Safety Certificate for the KV School Building, Staff Quarters
and Boundary Wall.**

Reference:-i) Your letter No-F.240112-1 /2018-19/KVS(JR)admn(part-1)

Dt:-18-04-2018.


ii) Asstt. Executive Engineer report No-CSD/1/72.

Dt:-26-05-2018.

Sir,

On the subject cited above, it is to intimate, that on site verification, by the field staff it is noticed that as per visual observation there is no any damage to the main building structure, and is safe for use. However the compound walling approximately length of 70mtr is needs to be re-constructed. As it was damaged due to flood accured in 2010.

Yours faithfully,


Executive Engineer,
Const. Division
Construction Division Leh.

Copy to the:-

1. Asstt. Executive Engineer Sub Div-Ist for information. This is in reference to his report no. captioned above.